



Parcel C RU-C5 Building 134 Update

BCT Meeting April 26,2011



RU-C5 Groundwater Treatability Study (TS) Overview



- 1. Pre-Design Characterization/Baseline Sampling
- 2. Treatment Component (TC) TS Design Finalization
- 3. TC 1 and 3, Implementation of Hydraulic Fracturing and EHC Emplacement in Source Area and Plume
- 4. TC2: Thermal Conduction Heating (TCH)
- 5. TC3: LactOil Polish



TC2: Thermal Conduction Heating




- Details of Shutdown and Performance
- Post –Thermal Sampling





TC2: TCH Treatment System As-Built








Recent Conditions Near the RU-C5 TS Area









Photograph 2 – Interior of the heater box in Well HO-4






Mass Removal Rate – based on PID



Mass Removal






Mass Removal rate - PID vs. Lab



Mass Removal and Discharge






Well Field PID Readings




Wellfield PID Readings





Well Field Summa Influent Concentrations







TC2: TCH Conclusions



Thermal system heaters were shut down Apr. 5, 2011, and SVE system operated from Apr. 14-22, 2011.

- Summary of Operations:
 - 1,2-DCB went from 7 lb/day (Mar. 22) to 2.6 lb/day (Mar. 31) to current 0.05 lb/day (Apr. 15).
 - 1,4-DCB went from 1.8 lb/day to 0.6 lb/day to current 0.02 lb/day.
 - PCE went from 2.5 lb/day to 1.0 lb/day to current 0.06 lb/day.



TC2: TCH Conclusions




- April 4 WebEx Decisions:
 - Run TCH to April 21 and SVE to May 2
 - Eliminate LactOil polish in TC3
- Because of the recent field events cut TCH operations short
 - TCH shortened to April 5 and SVE to April 22
 - Continue LactOil polish in TC3
- TC2 System Demobilization: May 2011
 - Will evaluate heater casings and liners.
 - Source of flammable gasses will be investigated through soil and soil gas sampling.



Details of Post-Thermal Sampling



- 40 soil samples from 8 borings will be collected at locations near pre-thermal borings and be analyzed for:
 - VOC, SVOC, Metals, TPH (total extractable)
 - Using high-temperature sampling protocol
- Soil gas samples collected from SVE influent (last one Apr. 20) and PMP-1
- Groundwater sampling (IR25MW62A, -63A, 64A and 65B) for comprehensive suite of VOCs, SVOCs, TPH, Metals





TC3: Polish Injection Design Summary



- Design Parameters
- Injection Locations
- Schedule





TC3: Polish Injection Design Parameters



- 1. Use LactOil- combination of lactate (35%) and a microemusified vegetable oil (45%).
- 2. Based on CDM and the Shaw Treatability Tests, target in situ concentration ~1000 mg/L carbon.

Design Injection Parameters	
Target ROI	5 ft
Target Depth Interval- A aquifer	18-21 ft bgs (~ to bay mud)
Injection Concentration	2% v/v, or 16 g LactOil/L
Flow Rate	o.5 gpm
Effective Porosity (assumed)	0.15
Volume per Well	881 gallons
Total Volume	7048 gallons
Injection Time	29 hours



TC3: LactOil Polish at IR25MW11A and IR25MW68A



.005 mM TOTAL CHLORINATED VOC MOLAR CONCENTRATION

.05 mM TOTAL CHLORINATED VOC MOLAR CONCENTRATION

0.1 mM TOTAL CHLORINATED VOC MOLAR CONCENTRATION


.03 mM TOTAL CHLORINATED VOC MOLAR CONCENTRATION

.06 mM TOTAL CHLORINATED VOC MOLAR CONCENTRATION

- GROUNDWATER MONITORING WELLS
- SOURCE AREA FRACTURE WELLS
 - PLUME AREA FRACTURE WELLS

THERMAL TREATMENT AREA

HPS INJECTION WELLS





Schedule



- Comprehensive post—TS soil sampling: ~Apr. 27-29, 2011, (8 borings, 40 samples).
- TC3 polish injections: ~ week of May 10, 2011.
- TC3 Sampling Event 1: May 19, 2011.
- Comprehensive post—TS groundwater, soil gas:
 ~Jun. 14-20, 2011. (Thirteen groundwater monitoring wells and 5 soil vapor points).

• Draft Technical Report: BCT Review - Sept. 6, 2011.